

CERTIFICATE

This certifies, that the company

Valland S.p.A.
Corso Giacomo Matteotti, 8A
23900 Lecco (LC)
Italy

Is authorized to provide the product mentioned below

Description of product:

2-ways bolted top entry trunnion mounted ball valve series A31

In accordance with:

EN 61508:2010 Parts 1, 2, 4, 5, 6, 7

Registration No 20 21038 02 Test Report No PS-25037-24-M-02 File reference 21038-02

TÜV Nord Italia S.r.I (TÜV NORD Group) Via Turati, 70 – 20023 Cerro Maggiore (MI) – Italy Reportion & Certification Services Services NORD Italia St.

Validity from 2024-02-16 until 2027-02-15

www.tuev-nord.it

Cerro Maggiore, 2024-02-16 prodotto@tuev-nord.it



ANNEX

Annex 1, Page 2 of 2

To Certificate-Nr. 20 21038 02

Туре	A
HFT	0
Safety functions	 Close / Open upon the demand of the actuation system Close upon the demand of the actuation system, with inline tightness when in closed position
Mode of operation	Low Demand Mode

Random failure rates							
Configuration	Safety function	λ _{DU} [1/h]	λ _{DD} [1/h]	λ _s [1/h]			
Self-relieving / Double piston effect - No PST	1	4,95E-08	0,00E+00	0,00E+00			
Self-relieving / Double piston effect - With PST	1	4,45E-09	4,50E-08	0,00E+00			
Self-relieving - No PST	2	6,02E-08	0,00E+00	0,00E+00			
Self-relieving - With PST	2	1,52E-08	4,50E-08	0,00E+00			
Double piston effect - No PST	2	5,47E-08	0,00E+00	0,00E+00			
Double piston effect - With PST	2	9,68E-09	4,50E-08	0,00E+00			

Systematic capability	3 (Route 1 _s applied)					
	Route 1 _H :	Applied	Route 2 _H :	Applied		
Architectural constraints	single channelup to SIL 2up to SIL 3					
Remarks:	 Self-relieving configuration: both upstream and downstream seats shall be of self-relieving type (i.e. single barrier in the flow direction) Double piston effect configuration: at least downstream seat shall be of double piston effect type (i.e. double barrier in the flow direction) For further details, including environmental conditions, limitations of use, lifetime, failure rates traceability, mean repair times, common cause factors and systematic capability constraints, make reference to Safety Manual "Safety manual BV" 					

